

WisDOT Official List of Qualified Industry and Consultant Laboratories 11/20/2009

| Name and Address | Sampling/Testing and Related Activities Performed | Application Date | Effective Date | Expiration Date |
|--|--|-------------------|-----------------|-------------------|
| <p>AECOM 1035 Kepler Drive Green Bay, WI 54311-8320</p> <p>Robert J. Peeters bob.peeters@aecom.com 920-406-3130</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: WISDOT Test Method 1560, T166.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | December 17, 2008 | January 1, 2009 | December 31, 2009 |
| <p>AECOM 558 North Main Street Oshkosh, WI 54901</p> <p>Paul Timm paul.timm@aecom.com 920-235-0270</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 1140.</p> | December 17, 2008 | January 1, 2009 | December 31, 2009 |
| <p>AECOM 3909 Concord Avenue Weston, WI 54476</p> <p>Bill Anderson Bill.d.Anderson@aecom.com 715-355-4304</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 1140.</p> | December 17, 2008 | January 1, 2009 | December 31, 2009 |

| | | | | |
|--|---|-----------------------------|-----------------------------|------------------------------|
| <p>AECOM – Oshkosh Trailer Lab W8009 State Road 33 Beaver Dam, WI 53916</p> <p>Paul Timm Paul.timm@aecom.com 920-716-1338</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Soils: T88, T265.</p> | <p>June 22, 2009</p> | <p>June 22, 2009</p> | <p>December 31, 2009</p> |
| <p>American Engineering Testing, Inc. 4203 Schofield Avenue Suite #1 Schofield, WI 54476</p> <p>Gregory C. Owens gowens@amengtest.com 715-359-3534</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>January 05, 2009</p> | <p>January 05, 2009</p> | <p>December 31, 2009</p> |
| <p>American Engineering Testing, Inc. 360 Garfield Avenue Duluth, MN 55802</p> <p>Andrew E. Edlund aedlund@amengtest.com 218-722-4323</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T277, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 5, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|--------------------------|------------------------|--------------------------|
| <p>B. R. Amon & Sons W2950 Hwy. 11 Elkhorn, WI 53121</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Permeability-WisDOT Test Method, WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Soils: T89, T90, T99.</p> | <p>December 31, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>B.R. Amon & Sons W2950 Hwy 11 Elkhorn, WI 53121</p> <p>Field Satellite Lab #s: 183.</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, ASTM D 4791.</p> | <p>December 31, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>B.R. Amon & Sons W2950 Hwy 11 Elkhorn, WI 53121</p> <p>Trailer Lab #: 181, 185.</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D 4791.</p> | <p>December 31, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>B.R. Amon & Sons W2950 Hwy 11 Elkhorn, WI 53121</p> <p>Field Satellite Lab #: 1341</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>December 31, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|------------------|-----------------|-------------------|
| <p>Bacco Construction Company P.O. Box 458 N3660 N U.S. 2 Iron Mountain, MI 49801</p> <p>Brian Vuorinen brianv@baccoconstruction.com 906-774-4064</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | December 1, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Bacco Construction Company Trailer Lab #1551.</p> <p>Brian Vuorinen brianv@baccoconstruction.com 906-774-4064</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | December 1, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Bacco Construction Company Trailer Lab #1555.</p> <p>Brian Vuorinen brianv@baccoconstruction.com 906-774-4064</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | December 1, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Barron County Highway Department 260 North 7th Street P.O. Box 139 Barron, WI 54812</p> <p>John Dietrich Sandra.perry@co.barron.wi.us 715-637-3755</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | March 31, 2009 | March 31, 2009 | December 31, 2009 |
| <p>Barron County Highway Department- Crusher 260 North 7th Street Barron, WI 54812</p> <p>Jeff Outcalt Sandra.perry@co.barron.wi.us 715-637-3755</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> | April 8, 2009 | April 8, 2009 | December 31, 2009 |

| | | | | |
|---|---|--------------------------|-------------------------|--------------------------|
| <p>Bjoin Limestone Inc. 7308 W. State Rd. 11 Janesville, WI 53548</p> <p>Justin Kraft bjoinstone@jvl.net 608-876-6959</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), WISDOT fracture (coarse), T27, T90, T248, T255, ASTM D4791.</p> <p>Soils: T88, ASTM D 1140.</p> | <p>April 2, 2009</p> | <p>April 2, 2009</p> | <p>December 31, 2009</p> |
| <p>Bloom Consultants, LLC 600 W. Fulton Street Suite 701 Chicago, IL 60661</p> <p>Marla Weiss mweiss@bloomcos.com 312-876-9500</p> | <p>Aggregate: T11, T27, T89, T90, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T309.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T265, ASTM D422, ASTM D1140.</p> | <p>November 11, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Braun Intertec Corporation 2309 Palace Street La Crosse, WI 54603</p> <p>Scott Willinger swillinger@braunintertec.com 608-781-7277</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: WisDOT Test Method 1560, T166.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>January 15, 2009</p> | <p>January 15, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|--------------------------|------------------------|--------------------------|
| <p>Braun Intertec Corporation Metro Materials Lab 11001 Hampshire Avenue South Bloomington, MN 55438</p> <p>Caerhl Irey cirey@braunintertec.com 952-995-2000</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 03, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>BT², Inc. 2830 Dairy Drive Madison, WI 53718</p> <p>Debra Nelson dnelson@bt2inc.com 608-224-2830</p> | <p>Aggregate: AASHTO T2 (WISDOT modified).</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> | <p>November 19, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>CGC, Inc. * 2921 Perry Street Madison, WI 53713</p> <p>Kim J. Lewis klewis@cgcinc.net 608-288-4100</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D422, ASTM D 1140.</p> | <p>November 19, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|-------------------|-----------------|-------------------|
| <p>CGC, Inc. 336 S. Curtis Rd. West Allis, WI 53214</p> <p>Kim Lewis cgc2@execpc.com 414-443-2000</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309.</p> <p>Soils: T88, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | December 12, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Cedar Lake Sand & Gravel CO., Inc. 5189 Aurora Road, Hwy 41 Hartford, WI 53027</p> <p>James Van Someren 262-644-5125</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> <p>Soils: T88.</p> | December 30, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Cemstone Materials Lab 1370 Troutbrook Circle St. Paul, MN 55117</p> <p>Kim-tien Nguyen nrgc@cemstone.com 651-688-9292</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D 4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> | December 5, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Cemstone Ready Mix Lab New Richmond Plant 1190 County Road G New Richmond, WI 54017</p> <p>Dave Horejsi nrgc@cemstone.com 800-555-9415</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> | December 5, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Chequamegon Bay Engineering, Inc. 211 6th Street West Ashland, WI 54806</p> <p>William Kurtz bkurtz@cheqbayeng.com 715-682-6004</p> | <p>Concrete Mix: T22, T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T309, R39.</p> | June 17, 2009 | June 17, 2009 | December 31, 2009 |

| | | | | |
|---|---|--------------------------|------------------------|--------------------------|
| <p>Chippewa Concrete Services, Inc. 3030 110th Street Chippewa Falls, WI 54729</p> <p>Barry Bohman bbohman@charterinternet.com 715-723-5004</p> | <p>Concrete Mix: T22, T23, T119, T152-Air Meter calibration, T152-Air Content, T309.</p> | <p>November 18, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Chippewa County Highway Dept. Lab 801 E Grand Avenue Chippewa Falls, WI 54729</p> <p>Richard L. Kern Rkern@co.chippewa.wi.us 715-726-7914</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WisDOT Fracture (Coarse agg). T11, T27, T85, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p> <p>Concrete Mix: T23, T119, T141, T152, T309, R39.</p> | <p>December 15, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Chosen Valley Testing, Inc. 135 Buchner Place La Crosse, WI 54603</p> <p>Kraig McCoy kmccoy@chosenvallytesting.com 608-782-5505</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WisDOT Fracture (Coarse agg). T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 2, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|--------------------------|------------------------|--------------------------|
| <p>Coleman Engineering Company 635 Circle Drive Iron Mountain, MI 49801</p> <p>Graham Donahue gdonahue@coleman-engineering.com 906-774-3440</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WisDOT Permeability, WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D 4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T231, T309.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 30, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Cooper Engineering Company, Inc. 2600 College Drive P.O. Box 230 Rice Lake, WI 54868-0230</p> <p>Benny Walker walker@cooperengineering.net 715-234-7008</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T231, T309, R39.</p> <p>Soils: T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 1, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>County Materials Corporation 205 North Street Marathon, WI 54448</p> <p>Mike Strong Mike.strong@countymaterials.com 715-848-1365</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse Agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D 4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104, T103, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309, R39.</p> | <p>December 08, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|------------------------------|----------------------------|------------------------------|
| <p>County Materials Corporation 1203 70th Ave Roberts, WI 54023</p> <p>Ms. Claudette Wagner Claudette.wagner@countymaterials.com 715-749-2274</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309.</p> | <p>November 6, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>CQM, Inc. Construction Quality Management 2679 Continental Drive Green Bay, WI 54311-6627</p> <p>Bob Rouse rouse@cqminc.com 920-465-3911</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 17, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>CRM Laboratories 1725 Gillette Place La Crosse, WI 54601</p> <p>Brad Rugg Brad.rugg@croell.com 608-781-3200</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), T11, T27, T84, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> | <p>April 9, 2009</p> | <p>April 9, 2009</p> | <p>December 31, 2009</p> |
| <p>Duffek Sand & Gravel, Inc. (Lab #1) 1625 West Center Street Antigo, WI 54409</p> <p>Brian T. Braun duffek@netprosbb.net 715-623-7616</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT Permeability, WISDOT Fracture (Coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Soils: T89, T90, T99, T180.</p> | <p>December 24, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Duffek Sand & Gravel, Inc. (Lab #2) 1625 West Center Street Antigo, WI 54409</p> <p>Brian T. Braun duffek@netprosbb.net 715-623-7616</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT Fracture (Coarse), T11, T27, T248, T255, ASTM D4791.</p> | <p>December 24, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|--------------------------|------------------------|--------------------------|
| <p>Duffek Sand & Gravel, Inc. (Lab #3) 1625 West Center Street Antigo, WI 54409</p> <p>Brian T. Braun duffek@netprosb.net 715-623-7616</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT Fracture (Coarse), T11, T27, T248, T255, ASTM D4791.</p> | <p>December 24, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>ECS Illinois LLC 4718 N County Road Y Milton, WI 53563</p> <p>Rick Lou rlou@ecslimited.com 608-752-8050</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Content, T231, T309, R39.</p> <p>Soils: T88, T89, T90, T99, T180, T224, T268, ASTM D 422, ASTM D 1140.</p> | <p>December 1, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Evenson Construction Co., Inc. 4915 CTH A Valders, WI 54245</p> <p>Jim Van Someren evensonconstructiion@tds.net 920-775-4652</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> | <p>December 30, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>EPC Engineering & Testing 539 Garfield Avenue Duluth, MN 55802</p> <p>Chad Lowney clowney@epcduluth.com 218-727-1239</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, WISDOT fracture (coarse), T84, T85, T89, T90, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>June 22, 2009</p> | <p>June 22, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|--------------------------|------------------------|--------------------------|
| <p>Faulks Bros. Construction, Inc. E3481 Hwy. 22 & 54 Waupaca, WI 54981</p> <p>Brian Bucholz brian@waupacasand.com 715-258-8566</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> | <p>November 5, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Frank Bros. Inc. 6717 Hyw 59 East Milton, WI 53563</p> <p>Roy Frank eldirty@charter.net 608-868-2592</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>April 28, 2009</p> | <p>April 28, 2009</p> | <p>December 31, 2009</p> |
| <p>F. Radandt & Sons Highway Q Pit Laboratory 12415 Highway Q Two Rivers, WI 54241</p> <p>Josh Radandt 920-755-2131</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T90, ASTM D4791.</p> | <p>November 17, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>G. A. T. S. 327 N. 3rd St. Muscoda, WI 53573</p> <p>Keith Werthwein KEITHWERTHWEIN@CENTURYTEL.NET 608-574-6201</p> | <p>Aggregate: WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T152- Air meter Calibration, T152-Air Content, T309, R39.</p> <p>Soils: T88, T89, T90, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 30, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|--------------------------|-------------------------|--------------------------|
| <p>Gestra Engineering, Inc. 1626 W Fond Du Lac Avenue Milwaukee, WI 53205</p> <p>Mark Skiba mskiba@gestrainc.com 414-933-7444</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 5, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Gestra Engineering, Inc. 1626 W Fond Du Lac Avenue Milwaukee, WI 53205</p> <p>Mark Skiba mskiba@gestrainc.com 414-933-7444</p> | <p>Aggregate: T11, T27, T89, T248.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152-Air Content, T152-Air Meter Calibration, T231, T309.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T224, T265.</p> | <p>November 4, 2009</p> | <p>November 4, 2009</p> | <p>December 31, 2009</p> |
| <p>GeoTest, Inc. * 2135 S. 116th Street West Allis, WI 53227</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Permeability-WisDOT Test Method, WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T277, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 30, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|--------------------------|------------------------|--------------------------|
| <p>GeoTest, Inc. W6243 Constructor Dr. Unit A Appleton, WI 54914</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152-Air Content, 152-Aggregate Correction, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>April 10, 2009</p> | <p>April 10, 2009</p> | <p>December 31, 2009</p> |
| <p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobil Lab #1</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152-Air Content, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 30, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #2</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152-Air Meter Calibration, T152-Air Content, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 30, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #3</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152-Air Content, T198, T309.</p> | <p>December 30, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|-------------------|-----------------|-------------------|
| <p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #4</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | December 30, 2008 | January 1, 2008 | December 31, 2008 |
| <p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #7</p> <p>Mr. Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | November 5, 2008 | January 1, 2009 | December 31, 2009 |
| <p>GeoTest, Inc. 612 N. Sawyer Road Oconomowoc, WI 53066</p> <p>Trailer Lab HMA 1</p> <p>Mr. Jeff Anderson janderson@888geotest.com 414-321-8378</p> | <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | November 5, 2008 | January 1, 2009 | December 31, 2009 |

| | | | | |
|--|---|--------------------------|--------------------------|--------------------------|
| <p>Giles Engineering Associates, Inc. N8 W22350 Johnson Drive Suite A1 Waukesha, WI 53186</p> <p>Charles S. Gresser, P.E. cgresser@gilesengr.com 262-544-0118</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: WisDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T277, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>January 29, 2009</p> | <p>January 29, 2009</p> | <p>December 31, 2009</p> |
| <p>Great Lakes Soil & Environmental Consultants, Inc. * 600 Territorial Drive Suite G Bolingbrook, IL 60440</p> <p>Anshu Balekai abalekai@greatlakessoil.com 603-754-8700</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), Permeability–WisDOT Test Method, WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>February 13, 2009</p> | <p>February 13, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|-------------------|-------------------|-------------------|
| <p>Great Lakes Soil & Environmental Consultants, Inc. 5008 © W Ashland Way Franklin, WI 53132</p> <p>Anshu Balekai abalekai@greatlakessoil.com 414-614-8003</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), Permeability–WisDOT Test Method, WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | February 13, 2009 | February 13, 2009 | December 31, 2009 |
| <p>Gremmer & Associates 120 North Wilshire Blvd Stevens Point, WI 54481</p> <p>Scott Hintz s.hintz@gremmerassociates.com 715-341-4363</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248.</p> <p>Concrete Mix: T119, T141, T152-Air Meter Calibration, T152-Air Content, T309.</p> | February 3, 2009 | February 3, 2009 | December 31, 2009 |
| <p>Haas Sons, Inc. Construction Materials Lab 203 E. Birch Thorp, WI 54771</p> <p>Linda Tichna Charlene@haas4.com 715-669-5469</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> | December 31, 2008 | January 1, 2009 | December 31, 2009 |
| <p>IIW Engineers & Surveyors, P.C. 4155 Pennsylvania Avenue Dubuque, Iowa 52002-2628</p> <p>Bob Baumhover r.baumhover@iiwengr.com 563-556-2464</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | November 4, 2008 | January 1, 2009 | December 31, 2009 |

| | | | | |
|---|--|--------------------------|------------------------|--------------------------|
| <p>Independence Ready Mix Conc. Co. P.O. Box 127 Independence, WI 54747</p> <p>Mike Kupka indeereadymix@triwest.net 715-985-3118</p> | <p>Aggregate: WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> | <p>November 17, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>James Peterson Sons, Inc. N2251 Gibson Drive Medford, WI 54451</p> <p>Ron Demulling ronjpsinc@tds.net 715-748-3035</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T90, T248, T255, ASTM D4791.</p> | <p>November 6, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Jewell Associates Engineers, Inc. 560 Sunrise Drive P.O. Box 995 Spring Green, WI 53588</p> <p>Ralph J. Liegel Ralph.liegel@jewellassoc.com 608-588-7484</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> | <p>June 22, 2009</p> | <p>June 22, 2009</p> | <p>December 31, 2009</p> |
| <p>J Z Consulting N6098 CTH P Crivitz, WI 54114</p> <p>James L. Zwick jimzwick@webcntrl.com 715-854-2121</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (coarse agg.), T11, T27, T84, T89, T90, T248, T255, ASTM D4791.</p> | <p>December 08, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>John S. Olynick, Inc. N 7918 Hwy 73 Gilman, WI 54433</p> <p>Jacquie Ludescher olynick@centurytel.net 715-668-5211</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309.</p> | <p>November 19, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|--------------------------|------------------------|--------------------------|
| <p>Kapur & Associates, Inc. 700 Eagle Nest Boulevard Suite D Rothschild, WI 54474</p> <p>Joel weber jwebrer@kapur-associates.com 715-359-7764</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T225, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> <p>Soils: T88, T99, T180.</p> | <p>December 16, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>KL Engineering, Inc. 5950 Seminole Centre Court Suite 200 Madison, WI 53711</p> <p>Lance Williston lwilliston@klengineering.com 608-663-1218</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T309.</p> <p>Soils: T88, T265, ASTM D1140.</p> | <p>December 12, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>KL Engineering, Inc. N7149 547th Street Menomonie, WI 54751</p> <p>Field Lab #1</p> <p>Chris Ehlert cehlert@klengineering.com 715-829-1266</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T309.</p> <p>Soils: T88, T265, ASTM D1140.</p> | <p>December 12, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>KL Engineering, Inc. Intersection of STH 78 & STH 39 Blanchardville, WI 53516</p> <p>Field Lab #2</p> <p>Brad Cunningham bcunningham@klengineering.com 608-516-8051</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152- Air Content, T309.</p> <p>Soils: T88, T265, ASTM D1140.</p> | <p>December 12, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|-------------------|------------------|-------------------|
| <p>KL Engineering, Inc. W6790 CTH YY Neshkoro, WI 54960</p> <p>Field Lab #3</p> <p>Larry Beardslee lbeardslee@klengineering.com 608-516-3881</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T309.</p> <p>Soils: T88, T265, ASTM D1140.</p> | December 12, 2007 | January 1, 2009 | December 31, 2009 |
| <p>The Kraemer Company, LLC 820 Wachter Avenue Plain, WI 53577</p> <p>Mark Sander marks@tkcllc.com 608-546-2255</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), Permeability–WisDOT Test Method, WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 13.9), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL’s Proficiency Sample Program.</p> <p>Soils: T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | January 13, 2009 | January 13, 2009 | December 31, 2009 |
| <p>The Kraemer Company, LLC 820 Wachter Avenue Plain, WI 53577</p> <p>Trailer Laboratories #s: 7663; 7675, 7679; 7858, 7859, 7862.</p> <p>Mark Sander marks@kcllc.com 608-546-2255</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), Permeability–WisDOT Test Method, WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> | January 13, 2009 | January 13, 2009 | December 31, 2009 |
| <p>Langlade County HWY Dept. 1521 Arctic Street Antigo, WI 54409-2399</p> <p>Eugene Rogatzki cwells@co.langlade.wi.us 715-627-6272</p> | <p>Aggregate: AASHTO T2, Fracture (Coarse Agg.), T11, T27, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | April 30, 2009 | April 30, 2009 | December 31, 2009 |

| | | | | |
|---|---|-------------------------|-------------------------|--------------------------|
| <p>Lincoln County HWY Dept. 100 Cooper Street Merril, WI 54487</p> <p>Randy Scholz rscholz@co.lincoln.wi.us 715-536-0352</p> | <p>Aggregate: AASHTO T2, Fracture (Coarse Agg.), T11, T27, T248, T255, ASTM D4791.</p> | <p>July 6, 2009</p> | <p>July 6, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 608-779-6392</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104, T103, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 1140.</p> | <p>January 29, 2009</p> | <p>January 29, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company Arnot QC Lab American Asphalt 4807 Custer Road Steven's Point, WI 54481</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 715-341-1953</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255, ASTM D 4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>February 2, 2009</p> | <p>February 2, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company Amery QC Lab 768 US Highway B Amery, WI 54001</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 715-268-6465</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 30, 2009</p> | <p>January 30, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|-------------------------|-------------------------|--------------------------|
| <p>Mathy Construction Company Mosinee QC Lab 1116 Happy Hollow Road Mosinee, WI 54455</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 715-693-5279</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT 1560, T166, T209, T269, T312.</p> | <p>January 29, 2009</p> | <p>January 29, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company Fox Ridge QC Lab S. 4383 Hwy 12 Baraboo, WI 53913</p> <p>Erv Dukatz, PhD, P.E. edukatz@mathy.com 608-356-3742</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>February 2, 2009</p> | <p>February 2, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company Marshfield QC Lab 11928 Stadt Road Marshfield, WI 54449</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 608-384-9312</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> | <p>February 2, 2009</p> | <p>February 2, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company New Richmond QC Lab 1190 Co. Rd. G New Richmond, WI 54017</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 715-246-7019</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>February 2, 2009</p> | <p>February 2, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|-------------------------|-------------------------|--------------------------|
| <p>Mathy Construction Company Brown's bottom QC Lab 12567 English Mill Road Dubuque, IA 52001</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 563-583-1902</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 29, 2009</p> | <p>January 29, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company Plant 87 QC Lab W5380 State Road 80 Eau Claire, WI 54701</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 715-835-0167</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 30, 2009</p> | <p>January 30, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company AMC Pit 31 QC Lab 3189 Jopke Road Eau Claire, WI 54702</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 715-830-5954</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Concrete: T22, T23, T24, T119, T141, T152, T309, R39.</p> | <p>January 29, 2009</p> | <p>January 29, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company Plant 86 Lab 2601 Conoco Road La Crosse, WI 54601</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 608-783-2404</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 29, 2009</p> | <p>January 29, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|--------------------------|-------------------------|--------------------------|
| <p>Mathy Construction Company Hayward QC Lab 11154 N. Olson Road Hayward, WI 54843</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 715-234-2626</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Concrete: T22, T23, T24, T119, T141, T152, T309, R39.</p> | <p>February 2, 2009</p> | <p>February 2, 2009</p> | <p>December 31, 2009</p> |
| <p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650 Portable QC Lab Trailers: 44-28, 44-29, 44-38, 44-41, 44-42, 44-43, 44-44, 44-45, 44-46, 44-62, 44-63, 44-95, 44-97, 44-98, 44-99, 44-112, 44-113, 44-134.</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 608-792-2697</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>February 2, 2009</p> | <p>February 2, 2009</p> | <p>December 31, 2009</p> |
| <p>MCC, Inc. 4905 W Prospect Ave Appleton, WI 54912</p> <p>Scott Paque Scptt.paque@murphinc.org 920-749-3360 Ext 3079</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WISDOT Test Method), WISDOT fracture (coarse), T11, T27, T84, T85, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T309, R39.</p> <p>Soils: T90, T99.</p> | <p>December 15, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|-------------------|-----------------|-------------------|
| <p>Mead & Hunt Inc. * 6501 Watts Road Madison, WI 53719-2700</p> <p>Lew Kollmansberger Lew.kollmansberger@meadhunt.com 608-273-6380</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> <p>Soils: T88, T99, T180, T224.</p> | November 7, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Michels Materials - Brownsville Lab 817 West Main Street Brownsville, WI 53006</p> <p>Eric Zeinert ezeinert@michels-us.com 920-583-3132</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T89, T90, T99.</p> | November 10, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Michels Materials – Neenah Lab 700 Tullar Road Neenah, WI 54956</p> <p>Eric Zeinert ezeinert@michels-us.com 920-727-1688</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), WISDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> <p>Soils: T90, T99.</p> | November 10, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Michels Materials – Waterloo Lab W11184 Hubbleton Road Waterloo, WI 53594</p> <p>Eric Zeinert ezeinert@michels-us.com 920-478-2084</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), WISDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> <p>Soils: T90, T99.</p> | November 10, 2008 | January 1, 2009 | December 31, 2009 |

| | | | | |
|---|--|--------------------------|--------------------------|--------------------------|
| <p>Michels Materials Trailer Laboratories: D632, D741, D743, D1015 and D1021.</p> <p>Eric Zeinert ezeinert@michels-usa.com 920-583-3132</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability -WisDOT Test Method, WISDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> <p>Soils: T90, T99.</p> | <p>November 10, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Midwest Engineering Services, Inc. 821 Corporate Court Suite 102 Waukesha, WI 53189</p> <p>Daniel Anderson dandean@midwesteng.com 262-521-2125</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability (WisDOT Test Method), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>February 24, 2009</p> | <p>February 24, 2009</p> | <p>December 31, 2009</p> |
| <p>Modern Ready Mix 4980 West 6th Street Winona, MN 55987</p> <p>Michael Kohner mikekohner@hotmail.com 507-454-5093</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> | <p>November 12, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Northeast Asphalt, Inc. Larsen 4515 Cty. Rd. 11 Larsen, WI 54947</p> <p>Brett Stanton bstanton@neasphalt.com 920-757-7575</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 20, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|------------------------------|----------------------------|------------------------------|
| <p>Northeast Asphalt, Inc. De Pere 5118 Video Lane De Pere, WI 54115</p> <p>Brett Stanton bstanton@neasphalt.com 920-757-7575</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 20, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Northeast Asphalt, Inc. Shawano W5660 Castle Road Shawano, WI 54166</p> <p>Brett Stanton bstanton@neasphalt.com 920-757-7575</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 20, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Northeast Asphalt, Inc. Juneau W6134 Prospect Road Juneau, WI 53039</p> <p>Brett Stanton bstanton@neasphalt.com 920-757-7575</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 20, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Northeast Asphalt, Inc. Green Bay Laboratory 1524 Atkinson Drive Green Bay, WI 54303</p> <p>Brett Stanton bstanton@neasphalt.com 920-757-7575</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 20, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|--------------------------|------------------------|--------------------------|
| <p>Northeast Asphalt, Inc. W6380 Design Drive Greenville, WI 54942</p> <p>Trailer Labs: 15410, 05411, 05412, 05413, 05521, 354073, 354075, 354104</p> <p>Brett Stanton bstanton@neasphalt.com 920-757-7575</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Fracture (Coarse agg.), T11, T27, T84, T85, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 20, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Northeast Asphalt, Inc. Greenville Design Lab W6380 Design Drive Greenville, WI 54942</p> <p>Karl J. Runstrom krunstrom@neasphalt.com 920-757-7585</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T24, T119, T141, T152-Air Content, T152-Aggregate Correction.</p> <p>Soils: T88, T89, T90, T99.</p> | <p>November 03, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Northern Wisconsin-Based Engineers, Inc. 10593 Kansas Ave. P.O. Box 328 Hayward, WI 54843</p> <p>Heather Harrington heather@chegnet.net 715-634-4334</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T309.</p> <p>Soils: T88, T265, ASTM D 1140.</p> | <p>March 27, 2009</p> | <p>March 27, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|----------------------|----------------------|--------------------------|
| <p>Northwest Asphalt Products Inc 11710 W Hampton Ave Milwaukee, WI 53225</p> <p>Bill Kotz 414-466-0644</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Coarse agg.), T11, T27, T84, T85, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, WisDOT Test Method 1559, T166, T209, T269, T312.</p> <p>Soils: T90, T99, T180, T224.</p> | <p>April 6, 2009</p> | <p>April 6, 2009</p> | <p>December 31, 2009</p> |
| <p>Nummelin Testing Services, Inc. 3217 Whiting Avenue Stevens Point, WI 54481-0127</p> <p>Bruce Nummelin bnummelin@nummelintesting.com 715-341-7974</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability-WisDOT Test Method, WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D422, ASTM D 1140.</p> | <p>June 29, 2009</p> | <p>June 29, 2009</p> | <p>December 31, 2009</p> |
| <p>Nummelin Testing Services, Inc. 5620 Woodland Drive Waunakee, WI 53597</p> <p>Mike Krawczyk mkraczyk@nummelintesting.com 608-849-9120</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Permeability-WisDOT Test Method, WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D422, ASTM D 1140.</p> | <p>June 29, 2009</p> | <p>June 29, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|--------------------------|------------------------|--------------------------|
| <p>OMNI Associates, Inc. * One System Drive Appleton, WI 54914</p> <p>Paul R. Eggen, PG, CET paul.eggen@omni.com 920-735-6900</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 18, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Park View Sand & Gravel LLC 31844 Hwy D Rochester, WI 53167</p> <p>Mark A. Franklin mafranklin@illinoismining.com 262-534-4347</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Permeability (WisDOT Test Method), WISDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p> <p>Soils: T88, T90, T99, T180, T224, T265, ASTM D 422.</p> | <p>November 17, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Payne & Dolan, Inc. * Waukesha Design Lab N3 W23650 Badinger Rd. Waukesha, WI 53188</p> <p>Karl Runstrom krunstrom@payneanddolan.com 262-524-1731</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 03, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|----------------------|--------------------|----------------------|
| <p>Payne & Dolan, Inc.* Gladstone Lab 801 Clark Drive Gladstone, MI 49837</p> <p>Karl Runstrom krunstrom@payneanddolan.com 906-428-5113</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | November 03, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Payne & Dolan, Inc. Cedar Lake Lab Field Lab #15332 5189 Aurora Road Hartford, WI 53027</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-644-9924</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | January 9, 2009 | January 9, 2009 | December 31, 2009 |
| <p>Payne & Dolan, Inc. K & N Field Lab #154180 N250 N8097 Hillside Drive Sussex, WI 53089</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-246-4801</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | January 9, 2009 | January 9, 2009 | December 31, 2009 |
| <p>Payne & Dolan, Inc. Fitchburg Lab 154138 6145 Cottonwood Trail Fitchburg, WI 53719</p> <p>Signe Reichelt sreichelt@payneanddolan.com 608-271-8617</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | January 9, 2009 | January 9, 2009 | December 31, 2009 |

| | | | | |
|---|---|------------------------|------------------------|--------------------------|
| <p>Payne & Dolan, Inc. Waukesha Field Lab #154137 N250 W233 Hwy F, Waukesha, WI 53188</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-524-1932</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 9, 2009</p> | <p>December 31, 2009</p> |
| <p>Payne & Dolan, Inc. Franklin Field Lab # 154140 6211 Rawson Ave Franklin WI 53132</p> <p>Signe Reichelt sreichelt@payneanddolan.com 414-423-2542</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 9, 2009</p> | <p>December 31, 2009</p> |
| <p>Payne & Dolan, Inc. Muskego Field Lab # 154141 W217 S8415 Crowbar Road Muskego, WI 53150</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-662-3366</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 9, 2009</p> | <p>December 31, 2009</p> |
| <p>Payne & Dolan, Inc. Racine Field Lab # 154142 2020 Oakes Road Racine, WI 53406</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-884-7922</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 9, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|---|------------------------|------------------------|--------------------------|
| <p>Payne & Dolan, Inc. Kenosha Field Lab # 15377 1740 120th Ave. Kenosha, WI 53144</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-859-0569</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Payne & Dolan, Inc. Hustisford Field Lab # 15408 N2502 CTH R Hustisford, WI 53034</p> <p>Signe Reichelt sreichelt@payneanddolan.com 920-349-8584</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 9, 2009</p> | <p>December 31, 2009</p> |
| <p>Payne & Dolan, Inc. Saukville Field Lab # 15333 3792 Lakeland Dr Saukville, WI 53080</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-675-0490</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 9, 2009</p> | <p>December 31, 2009</p> |
| <p>Payne & Dolan, Inc. Vienna Lab # 154139 5416 Easy Street Waunakee, WI 53597</p> <p>Signe Reichelt sreichelt@payneanddolan.com 608-849-8943</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>January 9, 2009</p> | <p>January 9, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|--------------------------|------------------------|--------------------------|
| <p>Peters Concrete Company 1516 Atkinson Drive Green Bay WI 54303</p> <p>Perry Rose PCClab121@tds.net 920-494-3700</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT Fracture (Coarse), T11, T27, T84, T85, T90, T248, T255, ASTM D4791.</p> <p>Concrete: T22, T23, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T88, T90, T99, T180, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 4, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>P O B Materials 2927 Golden Glow Rd. Depere, WI 54115</p> <p>Lab # 1</p> <p>Jesse Houle jesseh@pobinc.com 715-344-9999</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T231, T309, R39.</p> | <p>July 23, 2009</p> | <p>July 23, 2009</p> | <p>December 31, 2009</p> |
| <p>P O B Materials 2927 Golden Glow Rd. Depere, WI 54115</p> <p>Lab P1</p> <p>Jesse Houle jesseh@pobinc.com 715-344-9999</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T231, T309, R39.</p> | <p>July 23, 2009</p> | <p>July 23, 2009</p> | <p>December 31, 2009</p> |
| <p>Premier Concrete Inc. 8431 Hwy 57 Baileys Harbor, WI 54202</p> <p>Jon Leach jleach@premierconcreteinc.com 920-839-1117</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), WISDOT Fracture (Coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete: T23, T119, T141, T152-Aggregate Correction, T309.</p> | <p>November 03, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|--------------------------|-------------------------|--------------------------|
| <p>Professional Service Industries, Inc. W228 N727 Westmound Drive Suite A Waukesha, WI 53186</p> <p>Michael Bolcek Michael.bolcek@psiusa.com 262-970-9022</p> | <p>Concrete Mix: T22.</p> | <p>February 9, 2009</p> | <p>February 9, 2009</p> | <p>December 31, 2009</p> |
| <p>QC Tech 315 76th Street Franksville, WI 53126</p> <p>Scott Wall qcmaterials@gmail.com 414-406-5839</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Permeability-WisDOT Test Method, WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T277, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T265, ASTM D 422, ASTM D 1140.</p> | <p>January 21, 2009</p> | <p>January 21, 2009</p> | <p>December 31, 2009</p> |
| <p>QUEST, LLC North Maple Street Junction City, WI 54443</p> <p>Lab # 1</p> <p>Mark W. Reed Mark.reed@questllc.biz 715-423-3525</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T309.</p> <p>Soils: T88, T265, ASTM D1140.</p> | <p>December 23, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>R E I Materials Laboratory 4080 N. 20th Avenue Wausau, WI 54401</p> <p>Tom Marschke tmarschke@reiengineering.com 715-675-9784</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T309.</p> <p>Soils: T88, T99.</p> | <p>December 19, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|------------------------------|----------------------------|------------------------------|
| <p>RJS Construction Group LLC/Johnson Materials Company 5300 Stinson Avenue Superior, WI 54880</p> <p>Lab Trailer Nos. 2913, 2915.</p> <p>David M. Lemke dlemke@rjs5300.com 715-394-7771</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T119.</p> <p>Soils: T88, T89, T90, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 12, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>River Valley Testing Corp. 1280 Parkview Road Green Bay, WI 54304</p> <p>Mark E. King, P.E. mking@rvtcorp.com 920-347-9040</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 12, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>River Valley Testing Corp. 979 Jonathan Drive, Suite A Madison, WI 53713</p> <p>Brad Wilder, P.E. bwilder@rvtcorp.com 608-222-9406</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T265, ASTM D 1140.</p> | <p>December 29, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>River Valley Testing Corp. 1060 Breezewood Lane, Suite 102 Neenah, WI 54956</p> <p>Jeremy A McConnell, P.E. jmccConnell@rvtcorp.com 920-886-1406</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>April 5, 2009</p> | <p>April 5, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|--------------------------|--------------------------|--------------------------|
| <p>River Valley Testing Corp. 1060 Breezewood Lane, Suite 102 Neenah, WI 54956</p> <p>Asphalt Lab 1</p> <p>Jeremy A McConnell, P.E. jmccconnell@rvtcorp.com 920-886-1406</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>April 5, 2009</p> | <p>April 5, 2009</p> | <p>December 31, 2009</p> |
| <p>Rock Road Companies, Inc. 301 W.B.R. Townline Rd. Beloit, WI 53511</p> <p>Steve Bloedow sbloedow@rockroads.com 608-752-8944</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT 1559, WisDOT 1560, T166, T209, T269, T312.</p> | <p>February 17, 2009</p> | <p>February 17, 2009</p> | <p>December 31, 2009</p> |
| <p>Rock Road Companies, Inc. 301 W.B.R. Townline Rd. Beloit, WI 53511</p> <p>Trailer Lab: 1</p> <p>Steve Bloedow sbloedow@rockroads.com 608-289-7365</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p> | <p>February 17, 2009</p> | <p>February 17, 2009</p> | <p>December 31, 2009</p> |
| <p>Rock Road Companies, Inc. W8512 CTH Y Monroe, WI 53520</p> <p>Steve Bloedow sbloedow@rockroads.com 608-289-7365</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), T11, T27, T248.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p> | <p>February 17, 2009</p> | <p>February 17, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|--------------------------|------------------------|--------------------------|
| <p>Rusk County Highway Dept. N6335 State Rd. 27 Ladysmith, WI 54848</p> <p>Phil Montwill pmontwill@ruskcountywi.us 715-532-0387</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>November 24, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Sheboygan County Highway Dept. 1211 N 23 St. Sheboygan, WI 53081</p> <p>Trailer Lab #6134</p> <p>Richard Landwehr gottoamg@co.sheboygan.wi.us 920-459-3822</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560.</p> | <p>November 6, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Soils & Engineering Services, Inc. * 1102 Stewart Street Madison, WI 53713-4648</p> <p>Duane E. Reichel, P.E. duane@soils.ws 608-274-7600</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), Permeability – WisDOT Test Method, WisDOT Fracture (Coarse agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 4, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|--------------------------|------------------------|--------------------------|
| <p>Team Engineering, Inc. 240 Main Street Loganville, WI 53943</p> <p>Steven A. Alt salt@teamenginc.com 608-727-2146</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Meter Calibration, T152-Air Content, T309.</p> | <p>November 24, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Tetra Tech, Inc. 555 South 72nd Avenue Wausau, WI 54401</p> <p>Paul Michling Paul.Michlig@tetrattech.com 715-845-4100</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>December 4, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Tetra Tech, Inc. N7315 CTH Y, Suite F Seymour, WI 54165</p> <p>Matt Ovans Mattew.ovans@tetrattech.com 920-833-2116</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T99, T180, T224, T265, ASTM D 1140.</p> | <p>December 5, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|-------------------------|------------------------|--------------------------|
| <p>Tetra Tech, Inc. 555 South 72nd Avenue Wausau, WI 54401</p> <p>Mobile Trailers W-1</p> <p>Paul Michling Paul.Michlig@tetratech.com 715-845-4100</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T255.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Content, T152-Aggregate Correction, T309, R39.</p> <p>Soils: T87, T88, T99, T180, T224, T265, ASTM D1140.</p> | <p>December 4, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Tetra Tech, Inc. 555 South 72nd Street Wausau, WI 54401</p> <p>Mobile Trailers W-2</p> <p>Paul Michling Paul.Michlig@tetratech.com 715-845-4100</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T255.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Content, T152-Aggregate Correction, T309, R39.</p> <p>Soils: T87, T88, T99, T180, T224, T265.</p> | <p>December 4, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Tetra Tech, Inc. 555 South 72nd Street Wausau, WI 54401</p> <p>Mobile Trailers W-3</p> <p>Paul Michling Paul.Michlig@tetratech.com 715-845-4100</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), T11, T27, T248.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> | <p>December 4, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|--------------------------|------------------------|--------------------------|
| <p>Tetra Tech, Inc. 1837 CTH OO Chippewa Falls, WI 54729-6519</p> <p>Joel J. Guanella Joel.guanella@tetrattech.com 715-832-0282</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T277, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 19, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Tetra Tech, Inc. 1837 CTH OO Chippewa Falls, WI 54729</p> <p>Mobile # 1</p> <p>Joel J. Guanella Joel.guanella@tetrattech.com 715-832-0282</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T309.</p> <p>Soils: T99, T224, ASTM D 422, ASTM D 1140.</p> | <p>November 19, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Tetra Tech, Inc. 1837 CTH OO Chippewa Falls, WI 54729</p> <p>Mobile # 2</p> <p>Joel J. Guanella Joel.guanella@tetrattech.com 715-832-0282</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T309.</p> <p>Soils: T99, T180, T224, ASTM D 422, ASTM D 1140.</p> | <p>November 19, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|---|--------------------------|------------------------|--------------------------|
| <p>Toki & Associates, Inc. 7100 W. Fond Du Lac Ave. Suite 201 Milwaukee, WI 53218-3847</p> <p>Olaitan Olapo toki@tokiandassociates.com 414-463-2700</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT Permeability, WisDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309.</p> | <p>November 25, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Trierweiler Construction & Supply Co., Inc. 406 East 29th Street, P O Box 1236 Marshfield, WI 54449</p> <p>Michael Hammitt mike@trierweilerco.com 715-305-5748</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T309, R39.</p> | <p>November 6, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Twin City Materials, Inc. 12252 40th Ave. Chippewa Falls, WI 54729</p> <p>Monte Mitchell 715-723-8527</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT Permeability, WisDOT fracture (coarse), T11, T27, T84, T85, T248, T255, ASTM D4791.</p> | <p>June 10, 2009</p> | <p>June 10, 2009</p> | <p>December 31, 2009</p> |
| <p>Twin Ports Testing Inc. * 1301 North Third Street Superior, WI 54880</p> <p>Ron E. Eastling ron.eastling@twinportstesting.com 715-392-7114</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | <p>November 3, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|--|--|--------------------------|-------------------------|--------------------------|
| <p>Vulcan Materials Company 5713 W Rawson Avenue Franklin, WI 53132</p> <p>Gina M. Parisi-Luedtke parisig@vmcmail.com 414-421-1518</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, ASTM D4791.</p> | <p>November 3, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Wabasha Sand, Gravel & Ready Mix 905 Church Ave. Wabasha, MN 55981</p> <p>Mike Kohner mikekohner@hotmail.com 507-454-5093</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), WisDOT fracture (coarse), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> | <p>November 12, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Westbrook Materials Laboratory 619 E. Hoxie St. & E4751 Rt. 2 Hwy 14 W, Spring Green, WI 53588</p> <p>Nancy Ringelstetter nringelstetter@westbrookeng.com 608-588-7866</p> | <p>Aggregate: AASHTO T2 (WisDOT modified), Permeability (Wisdot Test Method), WisDOT fracture (coarse), T11, T27, T89, T90, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309, R39.</p> <p>Soils: T90, T99, ASTM D 1140.</p> | <p>December 3, 2008</p> | <p>January 1, 2009</p> | <p>December 31, 2009</p> |
| <p>Wingra Stone Company Quality Control Lab 7391 County Highway PD Verona, WI 53593</p> <p>Charles Chvala Chuck.chvala@wingrastone.com 608-845-9695</p> | <p>Aggregate: AASHTO T2 (WISDOT Modified), Permeability WisDOT Test Method, WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> | <p>January 08, 2009</p> | <p>January 08, 2009</p> | <p>December 31, 2009</p> |

| | | | | |
|---|--|-------------------|------------------|-------------------|
| <p>Wisconsin Testing Laboratories, LLC W140 N5886 Lilly Road Menomonee Falls, WI 53051</p> <p>Jeffery G. Smith jsmith@witestlab.com 262-252-3300</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), WISDOT fracture (coarse), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p> | December 23, 2008 | January 1, 2009 | December 31, 2009 |
| <p>Yahara Materials, Inc. 6117 CTH K Waunakee, WI 53597</p> <p>Yahara Office Lab & Field Labs # 2263.</p> <p>Kevin Stuart KEVIN@YAHARA.COM 608-849-4162</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Course Agg.), T11, T27, T90, T248, T255, ASTM D4791.</p> | January 12, 2009 | January 12, 2009 | December 31, 2009 |
| <p>Yahara Materials, Inc. 315 Moravian Valley Rd Suite #9 Waunakee, WI 53597</p> <p>Kevin Stuart KEVIN@YAHARA.COM 608-849-4162</p> | <p>Aggregate: AASHTO T2 (WISDOT modified), Fracture (Course Agg.), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 4-25-50), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Soils: T87, T88, T89, T100, T265, ASTM D 1140.</p> | October 15, 2009 | October 15, 2009 | December 31, 2009 |

* Indicates that this laboratory is AASHTO accredited.