



06-05

Communication	Navigation	Services				
CTAF. . . . . 122.8 APP/DEP. . . . 120.15	<table border="1"> <tr> <td data-bbox="651 1388 953 1430"> <b>Elevation. . . . . 835'</b> </td> </tr> <tr> <td data-bbox="651 1430 953 1472">                     TPA. . . . . 1835'                 </td> </tr> <tr> <td data-bbox="651 1472 953 1514">                     VOR to Field:                 </td> </tr> <tr> <td data-bbox="651 1514 953 1556">                     114.5 BUU 218°/6 NM                 </td> </tr> </table>	<b>Elevation. . . . . 835'</b>	TPA. . . . . 1835'	VOR to Field:	114.5 BUU 218°/6 NM	FUEL: None  Airport Manager 262-248-8811
<b>Elevation. . . . . 835'</b>						
TPA. . . . . 1835'						
VOR to Field:						
114.5 BUU 218°/6 NM						
<p><b>NOTES: 1. RWY 5: RIGHT TRAFFIC. 2. AIRPORT CLOSED DEC. 1 TO APRIL 5. 3. ULTRALIGHT OPERATIONS PROHIBITED. 4. AIRPORT CLOSED TO JET AIRCRAFT 0430-1230Z. 5. FOR NOISE ABATEMENT USE RWY 23.</b></p>						