



06-05

Communication	Navigation	Services		
CTAF. . . . . 123.0 APP/DEP. . . . 119.5	<table border="1"> <tr> <td data-bbox="651 1388 953 1472"> <b>Elevation. . . . . 773'</b>                      TPA. . . . . 1773'                 </td> </tr> <tr> <td data-bbox="651 1486 953 1556">                     VOR to Field:                      109.6 MNM 098<sup>o</sup>/20 NM                 </td> </tr> </table>	<b>Elevation. . . . . 773'</b> TPA. . . . . 1773'	VOR to Field: 109.6 MNM 098 <sup>o</sup> /20 NM	FUEL: 100LL - Airport Office 920-854-9711
<b>Elevation. . . . . 773'</b> TPA. . . . . 1773'				
VOR to Field: 109.6 MNM 098 <sup>o</sup> /20 NM				
<b>NOTES:</b> 1. RWY 01-19 SLOPES IMMEDIATELY DOWN TO SOUTH - CANNOT SEE ONE END FROM THE OTHER.				